#### **Product sheet**

# Miniature connector



Product Contacts: 19, Female cable connector with

shielding ring, shieldable, cable outlet 4 –

6 mm, with UL approval


Pole 1

Area Article number M16 IP67 Series 423 99 5462 15 19


## Illustration




# **Scale drawing**



# **Contact Arrangement**



## **Attenuation characteristic**



You can find the item description and assembly instruction on the next page.

# **Technical data**

#### **Common values**

Connector Design Connector locking system Termination Wire gauge (mm) Wire gauge (AWG) Cable outlet Upper temperature Lower temperature Female cable connector screw Solder 0.25 mm<sup>2</sup> 24 4 - 6 mm 95 °C

-40 °C

## **Electrical values**

Rated voltage 60 V Rated impulse voltage 500 V Pollution degree Overvoltage category Material group Ш Rated current (40°C) 3 A Volume resistivity  $\leq 3~m\Omega$ EMV compliance shielded Degree of protection Mechanical operation > 500 mating cycles

#### **Material**

Material of contact CuSn (Bronze)
Contact plating Au (Gold)
Material of contact body PBT (UL 94 V-0)
Material of housing CuZn (Brass nickel-plated)

Contacts: 19, Female cable connector with shielding ring, shieldable, cable outlet 4– 6 mm, gold plated contacts, with UL approval



#### **Product sheet**

## Miniature connector




Product Contacts: 19, Female cable connector with

shielding ring, shieldable, cable outlet 4 –

6 mm, with UL approval

Pole

Area Article number M16 IP67 Series 423 99 5462 15 19



# Installation instructions / Mounting cutout

#### Gerade Version

(Ausführung mit Schirmklemmring)

- Druckschraube, Klemmkorb, Dichtung, Distanzhülse und ersten Schirmklemmring auffädeln.
- 2. Litzen abisolieren, Schirm aufweiten und zweiten Schirmklemmring auffädeln.
- Litzen anlöten, Distanzhülse montieren, die beiden Klemmringe mit dem Schirm zusammenschieben und überstehenden Schirm abschneiden.
- 4. Übrige Teile gemäß Darstellung montieren.

## Straight version

(Version with shield clamping ring)

- 1. Bead pressing screw, pinch ring, seal, distance shell and first shield clamping ring on cable.
- 2. Strip wires, widen shield and bead second shield clamping ring.
- Solder wires, snap distance shell, push the two shield clamping rings together and cutt off projecting shielding braid.
- 4. Assemble remaining parts according to picture.

