#### **Product sheet**

Pole

## Miniature connector



Product Contacts: 12, Cable plug connector with cable clamp, shieldable, cable outlet 4 – 6

mm, with UL approval


1

Area Article number M16 IP67 Series 423 99 5129 00 12

#### Illustration




# Scale drawing




## **Contact Arrangement**

-3,61

-1,34 -3,59



#### **Attenuation characteristic**



You can find the item description and assembly instruction on the next page.

# **Technical data**

#### **Common values**

Connector Design Connector locking system Termination Wire gauge (mm) Wire gauge (AWG) Cable outlet Upper temperature Lower temperature Cable plug connector screw Solder 0.25 mm<sup>2</sup> 24 4 - 6 mm 95 °C -40 °C

## **Electrical values**

Rated voltage 60 V Rated impulse voltage 500 V Pollution degree Overvoltage category Material group Ш Rated current (40°C) 3 A Volume resistivity  $\leq$  3 m $\Omega$ EMV compliance shielded Degree of protection Mechanical operation > 500 mating cycles

#### **Material**

 Material of contact
 CuZn (Brass)

 Contact plating
 Au (Gold)

 Material of contact body
 PBT (UL 94 V-0)

 Material of housing
 CuZn (Brass nickel-plated)

Contacts: 12, Cable plug connector with cable clamp, shieldable, cable outlet 4– 6 mm, gold plated contacts, with UL approval

#### **Product sheet**

# Miniature connector




Product Contacts: 12, Cable plug connector with

cable clamp, shieldable, cable outlet 4 - 6

mm, with UL approval

Pole

Area Article number M16 IP67 Series 423 99 5129 00 12



# Installation instructions / Mounting cutout

#### **Gerade Version**

(Ausführung mit Schirmklemmring)

- 1. Druckschraube, Klemmkorb, Dichtung, Distanzhülse und ersten Schirmklemmring auffädeln.
- 2. Litzen abisolieren, Schirm aufweiten und zweiten Schirmklemmring auffädeln.
- 3. Litzen anlöten, Distanzhülse montieren, die beiden Klemmringe mit dem Schirm zusammenschieben und überstehenden Schirm abschneiden.
- 4. Übrige Teile gemäß Darstellung montieren.

## Straight version

(Version with shield clamping ring)

- 1. Bead pressing screw, pinch ring, seal, distance shell and first shield clamping ring on cable.
- 2. Strip wires, widen shield and bead second shield clamping ring.
- 3. Solder wires, snap distance shell, push the two shield clamping rings together and cutt off projecting shielding braid.
- 4. Assemble remaining parts according to picture.

